



Date: 14th October 1996

V1.2A LINKING BUG

When an ESP2 console fitted with software version 1.2A is changed from Slave mode to Master mode the flash button response of the connected Slave console can become slow. To restore normal response it is necessary to Deep Clear the Master console after it has been in Slave mode.