

HOG1000/500 Echelon 1K

Moving Light Consoles

TBJLT097.doc



Date: 04 November 2004

Programmer LCD Replacements

The programmer LCD used in the Echelon 1K and early model HOG1000/500 became obsolete in 1999. The replacement LCD was not physically compatible with the old one and the PCB was revised to suit – **the correct LCD must be used to repair a PCB**. This information is detailed in TBJLT071.

The spare parts stock of original LCD modules (Jands #ZLC1200) has now been exhausted. Because the original display is no longer available, ECHPROG2 and ECHPROG3 cards must be completely replaced if the LCD is faulty.

Refer to the photograph below and Jands Tech Note TBJLT071 for further information.

